# QUALITY CONTROL

| | |
|---|---|
| Name of the Work: | Improvements to drains at Bagalagunte main road L/S W.No.14 |
| Job No: | 014-13-000011 |
| Work order No: | 27/17.06.2013 |
| BR No: | 335/31.08.2013 |

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed Two years back.

Assistant Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike

30/6/13
Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike